




# NUTS

## HEX SLOTTED NUTS



Normal Size or Basic Major Dia of Thread		F			G		H			T		S		Runout Of Bearing Surface FIM
		Width Across Flats			Width Across Corners		Thickness			Unslotted Thickness		Width of Slot		
		Basic	Max	Min	Max	Min	Basic	Max	Min	Max	Min	Max	Min	
3/8	0,375	9/16	0,562	0,551	0,650	0,628	21/64	0,337	0,320	0,21	0,19	0,15	0,12	0,018
7/16	0,438	11/16	0,688	0,675	0,794	0,768	3/8	0,385	0,365	0,23	0,21	0,15	0,12	0,018
1/2	0,500	3/4	0,750	0,736	0,866	0,840	7/16	0,448	0,427	0,29	0,27	0,18	0,15	0,019
5/8	0,625	15/16	0,938	0,922	1,083	1,051	35/64	0,559	0,535	0,34	0,32	0,24	0,18	0,021
3/4	0,750	1-1/8	1,125	1,088	1,299	1,240	41/64	0,665	0,617	0,40	0,38	0,24	0,18	0,023
7/8	0,875	1-5/16	1,312	1,269	1,516	1,447	3/4	0,776	0,724	0,52	0,49	0,24	0,18	0,025
1	1,000	1-1/2	1,500	1,450	1,732	1,653	55/64	0,887	0,831	0,59	0,56	0,30	0,24	0,027
1-1/8	1,125	1-11/16	1,688	1,631	1,949	1,859	31/32	0,999	0,939	0,64	0,61	0,33	0,24	0,030
1-1/4	1,250	1-7/8	1,875	1,812	2,165	2,066	1-1/16	1,094	1,030	0,70	0,67	0,40	0,31	0,033
1-1/2	1,500	2-1/4	2,250	2,175	2,598	2,480	1-9/32	1,317	1,245	0,86	0,82	0,46	0,37	0,039