




NUTS

REGULAR SQUARE NUTS



Nominal or Basic Major Dia. of Thread		F			G		H		
		Width Across Flats			Width Across Corners		Across Corners Thickness		
		Basic	Max.	Mm.	Max.	Mm.	Basic	Max.	Mm.
1/4	0,250	7/16	0,438	0,425	0,619	0,584	7/32	0,235	0,203
5/16	0,313	9/16	0,562	0,547	0,795	0,751	17/64	0,283	0,249
3/8	0,375	5/8	0,625	0,606	0,884	0,832	21/64	0,346	0,310
7/16	0,438	3/4	0,750	0,728	1,061	1,000	3/8	0,394	0,356
1/2	0,500	13/16	0,812	0,788	1,149	1,082	7/16	0,458	0,418
5/8	0,625	1	1,000	0,969	1,414	1,330	35/64	0,569	0,525
3/4	0,750	1-1/8	1,125	1,088	1,591	1,494	21/32	0,680	0,632
7/8	0,875	1-5/16	1,312	1,269	1,856	1,742	49/64	0,792	0,740
1	1,000	1-1/2	1,500	1,450	2,121	1,991	7/8	0,903	0,847
1-1/4	1,250	1-7/8	1,875	1,812	2,652	2,458	1-3/32	1,126	1,062
1-1/2	1,500	2-1/4	2,250	2,175	3,182	2,956	1-5/16	1,348	1,276